
Document 23-2 Filed 12/16/2005 Claip # dge 1 07320301218 Coverage BLDG Policy # 6308271183

Ins Claim #

1

Risk, Front Elevation

PITTCRUBEL MAY 0 7 2003





Risk, Front Elevation

2

Insured

Document 23-2 Filed 12/16/2005 Claip # 2 07320301218 Coverage BLDG Policy # 6308271183


Ins Claim # F300301218

5

Risk, Left Elevation







Risk, Left Elevation

Insured

Document 23-2 Filed 12/16/2005 $^{\text{Claip}}_{\text{Policy}}$ # ge 3 $^{\text{F39}301218}_{\text{6308271183}}$

Ins Claim # F300301218

17

Roof, front upper offset





18

Roof, main lower slopes, temporary cover up and emergency repairs

Ins Claim # F300301218

37

Front porch ceiling and windows boarded up





38

Front porch ceiling

Insured


Document 23-2 Filed 12/16/2005 Flaip # ge 5 6308271183

F300301218 Ins Claim #

53

Rear porch siding and ceiling fan







54

Rear porch ceiling


Insured

Document 23-2 Filed 12/16/2005 Flain age 6 6720 Flain Flage 6 6308271183

Ins Claim # F300301218

55

Rear left exterior walls boarded







56

Rear porch concrete floor

Insured

Document 23-2 Filed 12/16/2005 Claip #ge 7 of 20301218 Coverage BLDG Policy # 6308271183

Ins Claim # F300301218

57

Left elevation







58

Side porch ceiling on left elevation

Photo: SheetJM Document 23-2 Filed 12/16/2005 Claim # of 20/201183

Ins Claim #

F300301218

Borden, Jonathan



61

Upper left elevation, broken windows





62

Framing on left elevation

Ins Claim # F300301218


Borden, Jonathan



63

Left elevation framing damaged





64

Interior windows boarded up on left elevation

Photo: 57265JM Document 23-2-grage illed 12/16/2005 Policy age 10 65 29 1183

F300301218


Ins Claim # F300301218

Borden, Jonathan Insured



65

Left elevation across side porch and columns





66

Left elevation brick veneer

Document 23-2

3-2 Filed 12/16/2005 Claip # 6308271188 Coverage BLDG Policy # 6308271183 Ins Claim #

F300301218

Borden, Jonathan

Insured




Photo -

Temporary Framing in basement to keep floor from collapsing





Photo -

Temporary framing to support the floor system above

Phôto: Sheet

R-2 Filed 12/16/2005 Claim # 6308271183 Document 23-2

F300301218 Ins Claim #

Insured

Borden, Jonathan



Photo -

Temporary power installed





Photo -

Framing in basement, View from main level down into basement from den, 1/2 of the floor collapsed into the basement


Photo: Sheet M

Document 23-2 Filed 12/16/2005 Claim # 13 0720 F300301218 Policy # 13 0720 6308271183

Ins Claim #

Photo -

F300301218




Temporary framing in basement. View from den above.

PHTShuller MAY 0 7 2003

Photo Special Document 23-2 Filed 12/16/2005 Clarge # 14 of 390301218 Policy # 6308271183

F300301218

Borden, Jonathan




1

Bedroom 1

Ins Claim #






Bedroom 1, closet area

Photo: SpectJM Document 23-2 Filed 12/16/2005 Policy # 15 03/08271183

Ins Claim # F300301218

Borden, Jonathan



3

Bedroom 1





- 2 -

Bedroom 1 hardwood flooring

Photo: 0 Sheet JM Document 23-2 Filed 12/16/2005 Claim # Page 16 01/201218 Policy # 16 03/08271183


Borden, Jonathan

Ins Claim #

F300301218

Wallpaper in Bedroom 1







Bedroom 2

Ins Claim #

9

Bedroom 2, Drywall







10

Bedroom 2

Document 23-2 Filed 12/16/2005 Page 18 0120 F300301218 Policy # 18 0120 6308271183


11

Ins Claim # F300301218

Front picture window in Bedroom 2







Bedroom 2, hardwood flooring

12

Document 23-2

3-2 Filed 12/16/2005 Clapate 19 570001218 Coverage BLDG Policy # 6308271183

F300301218 Ins Claim #

Insured

Borden, Jonathan



15

Master Bedroom





16

Master Bedroom

Borden, Jonathan

Insured

Document 23-2

Filed 12/16/2005 Clamege 20 660001218

Policy #

6308271183

Ins Claim # F300301218


Coverage BLDG



Master Bedroom, wallpaper boarder and exterior double doors







18

Master Bedroom